

Rubber Distributor Insulator

From David Adair, Oregon City, Oregon
Illustrated by Stephen Holt, Urbana, Illinois

Tiny Tips

From MAFCA Members

THE LOWER PLATE ON the distributor can ground out if the ignition cable is screwed in too tight. You can prevent this by gluing a $\frac{3}{8}$ " x $\frac{1}{2}$ " piece of bicycle inner tube to the opposite side of the contact point on the bottom plate.



Used inner tubes are readily available from most any bike shop.

When cut into thin slices, bicycle inner tubes also make a heavy duty rubber band. ☹

If you have a helpful tip about Model A restoration or maintenance to share with MAFCA members, please send it, with a photo or sketch, to the MAFCA office:

250 S. Cypress St.
La Habra, CA 90631

or email to: Restorer@mafca.com



Want More Tiny Tips?

Buy the book!

This 250-page paperback is chock full of practical ideas submitted over some 50 years.

Ordering information on pages 42-43. \$14